



一起220 kV线路保护误动事故的分析和处理

陈杰云

摘要: 介绍一起220 kV线路区外故障时保护误动的经过, 分析了事故发生的原因, 并对线路保护PTN线的接法进行改进。

关键词: 线路保护; 误动; PT中性点

Analysis and Treatment of a 220 kV Transmission Line Relay Misacton Fault

CHEN Jie-yun

Abstract: A misaction fault of a 220 kV transmission line relay at a 500 kV substation is introduced, and the cause of the fault is analyzed. Furthermore an improvement method for the PT neutral point connection is presented.

Key words: line protection; maloperation; PT neutral point

点击此处下载

关闭窗口